

Lead & Copper Rule Corrosion Control

AUTHORITY

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1						
2						
3	7.6				Y	
4						
5	7.5				Y	
6						
7	7.6				Y	
8						
9						
10	7.6				Y	
11						
12						
13	7.7				Y	
14	7.5				Y	
15						
16	7.4				Y	
17	7.5				Y	
18	7.5				Y	
19						
20	7.6				Y	
21	7.6				Y	
22						
23						
24	7.6				Y	
25						
26	7.4				Y	
27	7.5				Y	
28	7.5				Y	
29						
30						
31						
No = N = Excursion					Total N's	0

County: Josephine Agency: 5  
**Entry Point**  
**A**  
**PWS ID 4100971**  
**Cave Junction, City of**

Sample Period:  
 Month/Year April, 2023

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

**Minimum Water Quality  
 Parameter(s) as set by State:**

pH 7.3

Print Name: Steven Bethke  
 Signature: Steven Bethke  
 Date: 5-2-23

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp