

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	POL				Pol
2	POL			,	POL
3	POI	m vantaranara			181
4	P.J	anga da tratapat _{epo}		,	Y
5	PoL				801
6	7.8				У
7	7.9				W
8	Pd				N
9	POL				POL
10	00 (1001
11	746	A			У
12	8.2				سلر
13	8.3	, 100 Marini 1			V
14	8.3				V
15	8.3				N
16	POL		an deres		POL
17	8,3				٤
18	7.7	3			7
19	7.7				V
20	77				W
21	7.5	Company of the Compan		suprandationals	V
22	7.7				14
23.	901	5. 5.20 (100 (100 (100 (100 (100 (100 (100 (1	e spanie postania	j¶ Station istalia	POL
	TOC				Pol
25	PU	Same a service of the		4	Pol
26	PO				101
27	8.6				V
28	8.5	**************************************		5 5	Ú
28					1
30					
					X 11.

County: Douglas Agency: REGION 2	
ENTRY POINT	
EP-A	
PWS ID 4101092	
TILLER RANGER STATION	
riod: <u>Feb 2021</u>	
Month/Year	

Number of excursions during this month: (2)

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

•
•

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period

-Potemence -