

Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6					
7	7.4				y
8					
9					
10					
11					
12					
13					
14	7.4				y
15					
16					
17					
18					
19					
20					
21	7.5				y
22					
23					
24					
25					
26					
27					
28	7.3				y
29					
30					
31					

(No = N = Excursion) **Total N's**

<<Have
minimums
been met for
this day?

County: Clackamas Agency: CLACKAMAS COUNTY

ENTRY POINT

EP-A

PWS ID 4101125

MOUNTAIN VIEW CO-OP

Sample period: 11/2025
Month/Year

Number of excursions during this month: _____

(Over 9 excursions in 6 months is a violation.
Entry Point and Distribution excursions are
cumulative). An 'excursion' is any day in which the
water quality parameter(s) fall below the minimum
set by the State.

Reference _____

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.1

Print Name: Ricky White
Signature: R. White
Date & Phone#: 12-01-25 971-370-5330

Send to DWP within 10 days after end of
sampling period