

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	YIN
1	7,5				
.2	7.3				
3	7.7				
2 3 4 5 6	7.8				
5	フィブ				
6	9.0			•	
7	7.4	Trans. Bed Jan. 198. May 17 May 1			
8	7.3				
9	7.9				
10 11	7,9				
	7.4				
12	7.9		•		
13	7.4	other and the second			
14	1,3				
15	7,3 7,8 7,7	A			
16	2,7				
17	7.7				
18	7,2				
18 19	9.1				
20	80				
21	7.8				
22	7.7				
23	7,9			,	
24	7.3				A STATE OF THE PARTY OF THE PAR
25	7,9				
26	7.6				
27	7.7				
28	7.2				
29	7.3				
30	2.4				
31	7.3				
lo = N	! = Exc	ursion'	Total	N's	\mathcal{T}

< <have< th=""><th>County: Multinemsh Agency: MULTNOMAH COUNTY</th><th></th></have<>	County: Multinemsh Agency: MULTNOMAH COUNTY					
minimums	ENTRY POINT					
been met for this day?	EP-A					
PWS ID 4101267						
MANNA HOUSE CHURCH						
Sample period: 3/25						
Month/Year						

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference —	
Minimum Water Quality Parameter(s) as set by State: pH 7.2	
Print Name: Elay Herrera	A consequences
Signature: La Manine. Date & Phone#: 4/3/25	
Send to DWP within 10 days after end or sampling period	

OHA Drinking Water Program, PO Box 14350, Portland, OR 9729B-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/