

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	/ pH	Alk	Phos	Other	YIN
	1	7,9				
	.2	7.6				
	3	7.7	7			
	4	7,0	7			
	5	7.8				
	6	2.8				
	7	7.3				
	8	7.5				
	9	7,4				
	10	7.4				
	11	7.6				
	12	7.9				
	13	1.3	*			
	14	7.9				
	15	7.7				
	16	7.4				
	17	7.3				
	18	7.6				
	19	7.5				
	20	7.5				
	21	7,2				
	22	7,3				
	23	7.4				
	24	7.2				
	25	7.4				\dashv
	26	7.8				_
	27	7.7			-	\dashv
	28	7.4				-
	29	7,03			_	
1	30	7.4			_	_
	31				Co Sec	
(1)	lo = N	= Exc	ursion	Total	N's	0

	< <have< th=""></have<>
	minimums
	been met for this day?
1	

County: Multinomen Agency: MULTNOMAH COUNTY
ENTRY POINT

EP-A

PWS ID 4101267

MANNA HOUSE CHURCH

Sample period: 4/2025

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.2

Signature: La Manine.

Date & Phone#: 5 (1/2025

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 9729B-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/