

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Linn</th><th></th></have<>	County: Linn		
1	1		· ·			minimums	-		
2	1	<u> </u>				been met for	ENTRY	POINT	
3		†	ł			this day?	EP	- A	
4						· · · · · · · · · · · · · · · · · · ·	PWS ID 41	191671	
5						DIXIE ELEMENTARY SD 509.J			
6									
7						Samula na	riade T.L.	7 ~ `) 7	
8						Sample period: <u>July</u> 2021 Month/Year			
9									
10	Pum	b F	hally	GOF		Number of excursions during this month: (Over 9 excursions in 6 months is a violation.			
11	Cebr								
12						Entry Point and Distribution excursions are			
13						cumulative). A	n 'excursion' i	s any day in which the	
14	6.7		1.0		<u>\</u>	water quality p	arameter(s) fa	Il below the minimum	
15						set by the Stat	е.		
16									
17	6.7		4.0		+	Referer	nce		
18	6.7		1.0		Y				
19							inimum Wate	-	
20						P	arameter(s) a	s set by State:	
21	67		1.0		Ц		pH 6.7		
22							• []		
23							PO4 1. (C	Orthophosphate)	
24							- · <u> </u>		
25	6.7		1 . V		Y				
26 27									
	1 -		i o			Print Na	me: <u>Matt</u>	Hollidarp	
28 29	6.7		1.0			Signatur	e:		
30						Date & P	hone#: <u>8/</u>	10/2022	
31						Send to [OWP within 10	days after end of	
	sampling period								
(140 = 1	No = N = Excursion) Total N's								
	OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350								

Phone (971) 673-0405 Website: http://healthoregon.org/dwp/