

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

<u> </u>	Of numan services							
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
12/2	73					minimums	ENTRY POINT	
2/3	7.4					been met for this day?	EP-A	
2/6	7.3					Lang day:		
12/7	7.3				<u> </u>		PWS ID 4191707	
12/8	7.4					PL	EASANT VALLEY ELEM SD #55	
12/9	7.3		<u> </u>				, , ,	
12/10	7.4					Sample	period: <u>December 202</u>	
12/13	7.3				<u> </u>		Month/Year	
12/14	_		ļ			S = 1 = 2 1	pas closed to public 12-18	
12/1S	7.3		<u> </u>		ļ	School u	through of	
12/16	<u> </u>	ļ	<u> </u> -			1	excursions during this month:	
417	7.4	<u> </u>			-	(Over 9 excursions in 6 months is a violation. Entry		
			<u> </u>			1.	Distribution excursions are cumulative).	
		-	<u> </u>			•	on' is any day in which the water quality is) fall below the minimum set by the	
<u>}</u>				<u> </u>	<u> </u>	State.	sy tan below the triminant out by the	
	<u> </u>	<u> </u>	 		<u> </u>		e e	
			 		 	Pof	grance emailed 1-4-2022	
			 			1	erence emailed 1-4-2022 resubmitted 2-10-2022	
	<u> </u>	-	 		1	1	Minimum Water Quality	
							Parameter(s) as set by State:	
	1						pH 7.2	
	1						P'' [
					<u> </u>			
			ļ	ļ	ļ]		
		ļ	<u> </u>	<u> </u>		Drint No.	ma I Ani Ialainman	
	<u> </u>	<u> </u>		<u> </u>	_	Cimp - 4	ne: Loni Weinman e: Loni Mhi	
	<u> </u>			 	 			
	1	<u> </u>		<u> </u>	<u> </u>	- i	4-2022	
10 =	N = Ex	cursio	n) Tot a	al N's	0	l l	OWP within 10 days after end of	
sampling period								

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp