

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services						·		
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
4/1	7.5				<u> </u>	minimums been met for	ENTRY POINT	
4/2	7.5					this day?	EP-A	
43	7.5	<u> </u>		_			PWS ID 4191707	
4/4	7.5						•	
418	7.5					P	LEASANT VALLEY ELEM SD #55	
419	7.4		ļ		<u> </u>		N 1) 900U	
4/10	<u>√, ></u>	<u> </u>			<u> </u>	Sample period: Hpril 2024		
4/11	1.6						Month/Year	
7/17	7.7		-		<u> </u>			
7 5	1.5	<u> </u>	 	-		Number	of excursions during this month:	
711/	7 1	<u> </u>	<u>.</u>	_	-	(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
1/18 14/19	7 2				-			
4/25	73		 		 			
4/22	7 <u>u</u>	-	<u> </u>		 			
4/24	7 U	-	 			State.		
4/25	7.5							
4/26	7.4	<u> </u>				 Re	oference emailed 5-7-2024	
4/29	7.4							
4/3	7.4						Minimum Water Quality	
							Parameter(s) as set by State:	
							pH 7.2	
					<u> </u>			
		<u> </u>		<u></u>	<u> </u>			
		_		_				
					-	Print Na	ame: Loni Weinman	
-	<u> </u>	<u> </u>	<u> </u>	<u> </u>		Signatu	re: Lon Meinman	
		-	-	-	-	Data: F	5-7-2024	
	<u> </u>		<u> </u>	<u> </u>		_		
10 =	IN = EX	CUTSIO	n) Tot a	II N'S		sampling	DWP within 10 days after end of period	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp