

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services						·	-	
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
5/1	7.5					minimums	ENTRY POINT	
5/2	7.5					been met for this day?	EP-A	
5/3	7.6					Line day:		
5/6	7.4				_		PWS ID 4191707	
5/7	7.4					PL	EASANT VALLEY ELEM SD #55	
5/8	7.4				<u> </u>		00 000	
5)a	7.4				ļ	Sample period: May 2024 Month/Year		
5/10	7.4				<u></u>			
5/3	7.4	,	<u> </u>			L		
8/14	7.4		<u> </u>					
5/15	1.4		<u> </u>		 	1	excursions during this month:	
5/16	7.4		-	ļ <u>.</u>	 		cursions in 6 months is a violation. Entry	
517	7.5	<u> </u>	ļ		-	7.	Distribution excursions are cumulative).	
5/20	48	<u> </u>		<u> </u>	-	An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
5/21	<u> </u>	<u> </u>	ļ		-	State.	s) fail below the millimum set by the	
2/2	58		 		 			
5/25	7.5	<u> </u>	 	-	╂	, , , , , , , , , , , , , , , , , , ,	erence emailed 6-6-2024	
5/28	158		<u> </u>		<u> </u>	- Ren	erence ———————————————————————————————————	
5/30	107	_	 		+	-	Minimum Water Quality	
5/31	1-1-6	}	+	 	 	-	Parameter(s) as set by State:	
731	1.0	 	-	 	+	-		
			 	 	+	1	pH 7.2	
		 -	<u> </u>	 		-		
	1	 	 	 	1			
-	 	<u> </u>	┼	 	1	1		
	 		1	 	-	†		
	 		 	┼─	 	<u> </u>		
	 		+	 	†	Print Na	me: Loni Wenman	
		1	 			Signatur	e: 10 m 2	
	1 -			†	 		-6-2024	
No =	N = Ex	cursio	n) Tot a	al N's	1	<u> </u>	DWP within 10 days after end of	
	. —···		, . • • •	· · ·		sampling	•	