

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	рН	Alk	Phos	Sili	Y/N	← <have< p=""></have<>	County: Linn Agency: Linn	
8/2	7.4					minimums	ENTRY POINT	
8/5	7,5					been met for this day?	EP-A	
8/6	7.5					uns day!		
8/7	7.7	1.					PWS ID 4191707	
8/8	7.6	· ·				PLI	EASANT VALLEY ELEM SD #55	
8/9	7.7							
8/12	7.6			-		Sample	period: August 2124	
8/14	7.5					Sample period: Hugust 2124 Month/Year		
8/13	7.5							
8/19	7.4							
8/20	7.4					Number of	excursions during this month:	
8/21	7.5				ļ	(Over 9 exc	ursions in 6 months is a violation. Entry	
8/22	7.4					Point and D	istribution excursions are cumulative).	
826	7.6		ļ			An 'excursio	on' is any day in which the water quality	
8/27	75					_ ·	s) fall below the minimum set by the	
8/29	7.4	<u> </u>			<u> </u>	State.		
8/31)	7.3			ļ	1		rence emailed 9-10-24	
					-	Refe	erence Chillette Live	
			<u> </u>	ļ	ļ	-	Minimum Water Quality	
			 		<u> </u>		Parameter(s) as set by State:	
		<u> </u>	 _		<u> </u>		pH 7.2	
		<u> </u>				-		
ļ	ļ	 -	 	<u> </u>	-			
					-			
	ļ		<u> </u>	<u> </u>				
<u> </u>			ļ	ļ <u></u>	 	-		
<u> </u>	<u> </u>	<u> </u>	<u> </u>	ļ	_	Print Nan	ne: Loni Weinman	
<u> </u>	 	 -	<u> </u>	<u> </u>	 	Signature: Agn' M		
-	 	-		-	+	Date: 9	-10-24	
L	<u> </u>			 		≟,	MD within 10 days ofter and of	
NO =	No = N = Excursion) Total N's Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp