

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services							
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn
10/1	7.2					minimums been met for	ENTRY POINT
W 3	7.3					this day?	EP-A
10/4	7.4					Line day:	
10/7	7.6						PWS ID 4191707
10/8	7.5					P.	LEASANT VALLEY ELEM SD #55
199	7.6						0 111 = 20 111
10/10	7.6					Sample	e period: October 2024
10/11	7.6				<u> </u>		Month/Year
1914	7.3		<u> </u>		ļ	L	
10/17	7.3		<u> </u>		<u> </u>		
1918	74		ļ.		<u> </u>	Number o	of excursions during this month:
10/21	7.3	ļ 	 		-		ccursions in 6 months is a violation. Entry
1422	2.4		-	-	-		Distribution excursions are cumulative).
12/23	1.4	<u> </u>	ļ <u> </u>]	 	An 'excurs	sion' is any day in which the water quality r(s) fall below the minimum set by the
W24	1.5		 		<u> </u>	State.	(s) fail below the minimum set by the
10/28	14.5			<u> </u>		•	
18/1	1.4		<u> </u>	-	-		ference email en 11/12/2024
ļ		 	<u> </u>		1		rerence
		 - -			-	-	Minimum Water Quality
	<u> </u>	┼			 	-	Parameter(s) as set by State:
ļ		-				-	
<u> </u>		 _	 		 		pH 7.2
\vdash	 	├		-		1	
 	 	 					
 	╫		 		†	-	
	-	 	+				
	 	 	1	†		1 —	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	1		1		1	ì	ame: Lan Wenman
	 	†	<u> </u>	1		Signatu	re: 10n M W -
		1				Date: <u>↓</u>	1-12-2024
 No =	N = Ex	cursio	n) Tot a	al N's		Send to	DWP within 10 days after end of
			-			ے sampling	