

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
11/1	7.3					minimums	ENTRY POINT	
1/4	7.3	-				been met for		
11/5	7.4					this day?	EP-A	
11/10	7.3						PWS ID 4191707	
いりつ	7.4					PLEASANT VALLEY ELEM SD #55		
11/12	7.4							
11/13	7.5					Sample period: 1000mbu 2024 Month/Year		
1/14	7.3							
ű/iS	7.4					<u> </u>		
11/18	7.6				ļ			
11/19	77		<u>.</u>		<u> </u>	Number of excursions during this month:()		
11/20	7-6					(Over 9 excursions in 6 months is a violation. Entry		
1121	7.5					Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
11/22	7.3		<u> </u>					
11/25	7.4	<u> </u>	<u> </u>					
W26	7.5	<u></u>				State.		
					<u> </u>		rence emailed 12-3-24	
	ļ	<u> </u>	-			_ <i>Refe</i>	rence	
		<u> </u>					Minimum Water Quality	
	<u> </u>						Parameter(s) as set by State:	
<u> </u>	<u> </u>		-		-			
	 			<u> </u>	-	-	pH 7.2	
<u> </u>	 	-	 		<u> </u>	-		
	<u> </u>				+	-		
<u> </u>			<u></u>		1			
		<u> </u>	<u> </u>		+-			
	<u> </u>		<u> </u>	ļ	-			
-			 	<u> </u>	<u> </u>	Print Nam	ne: Loni Weinman	
	-	1	 		-		for mhi	
-	1	-	+-		+	Date: 12-		
No = N = Excursion) Total N's (') Send to DWP within 10 days after end of								
-	sampling period							