

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

	of	human se				<i>b</i> -		
Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Linn Agency: Linn</th></have<>	County: Linn Agency: Linn	
12/2	7.6					minimums	ENTRY POINT	
12/3	75					been met for		
12/10	7,4					this day?	EP-A	
12/9	73						PWS ID 4191707	
12/10	ウロ					PLEASANT VALLEY ELEM SD #55		
12/12	7.6							
12/13	フラ		1			Sample period: Detember 2024 Month/Year		
12/16	7.6							
12/17	7.4						Wiorian Foat	
12/19	7.6						$\widehat{}$	
					ļ	Number of	excursions during this month:	
				_		(Over 9 exc	cursions in 6 months is a violation. Entry	
							Distribution excursions are cumulative).	
						An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the		
						State.		
							emanded 1-15-25	
			<u> </u>			Refe	erence emailed 1-15-25	
					<u> </u>			
		<u> </u>	ļ		<u> </u>		Minimum Water Quality	
	ļ				<u> </u>		Parameter(s) as set by State:	
<u> </u>					<u> </u>		pH 7.2	
	<u> </u>	ļ	<u> </u>	<u> </u>	-			
	ļ	ļ	<u> </u>		-	-		
		<u> </u>		<u> </u>	 -			
		ļ	<u> </u>	<u> </u>	 			
		-	ļ		 	<u> </u>		
	<u> </u>	 	 -	-	_	Print Nar	ne: Loni Wanman	
<u> </u>		 	-{	ļ. —		Signature: 100 M Wi		
-		 -	 	 	 			
		<u> </u>	<u> </u>	<u> </u>	 	∫ Date: <u></u>		
No =	N = Ex	cursio	n) Tot a	al N's		1	WP within 10 days after end of	
						sampling	perioa	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: wwww.ohd.hr.state.or.us/dwp