

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

of numan services						»	·	
Day	pН	Alk	Phos	Sili	Y/N	' <have< th=""><th>County: Linn Agency: Linn</th></have<>	County: Linn Agency: Linn	
3/3	7.3					minimums	ENTRY POINT	
3/4	7.4					been met for this day?	EP-A	
3/5	7.5					Line day:		
3/6	7.4						PWS ID 4191707	
3/7	7.4					PL	EASANT VALLEY ELEM SD #55	
3/10	7.3				ļ		20 )	
3/11	7.4		ļ			Sample period: March 2025		
3/12	7.2						Month/Year	
3/13	7.3					<u> </u>		
3/14	7.5							
3/17	7.1		ļ			Number of	excursions during this month:	
3/18	7.2						cursions in 6 months is a violation. Enti	
3/19	7.5		<u> </u>		<u> </u>	1.	Distribution excursions are cumulative).	
3/21)	14		ļ		-		on' is any day in which the water qualit s) fall below the minimum set by the	
2/21	7.5		1	<u></u>	-	State.	s) fail below the minimum set by the	
7/25	1.4	<u> </u>	<u> </u>		-			
3/2	7.5		ļ		-	Det	erence Emailed 4-2-2025	
3/00	1/13	<u> </u>	<u> </u>		<del>                                     </del>	] Rele	erence	
308	72		<del>  -</del>				Minimum Water Quality	
3/21	72		<u> </u>				Parameter(s) as set by State:	
701	1.2	-	<del>                                     </del>	-			mt 1 7 2	
	\	<del>                                     </del>	<del></del>	<u> </u>			pH 7.2	
	<u> </u>	-	1			1		
	<u> </u>	-				,		
	<del>                                     </del>					]		
						Drint No.	ne: Loni Weinman	
			<u> </u>		<u> </u>	Signature: 400 M		
					<u> </u>	Signature	e. ywii i w	
	<u> </u>	<u> </u>		<u> </u>		」 Date: <u>너</u>	-2-2025	
10 =	N = Ex	cursio	n) <b>Tot</b> a	al N's	<u> </u>		OWP within 10 days after end of	
						sampling	period	

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp