

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	of	human se				5-	n	
Day	рН	Alk	Phos	Sili	Y/N		County: Linn Agency: Linn	
6/2	7.6					minimums	ENTRY POINT	
6/3	7.5	-				been met for this day?	EP-A	
6/4	7.4					Line day:		
6/5	7.4						PWS ID 4191707	
6/9	7.3					PL	EASANT VALLEY ELEM SD #55	
6/10	7.3							
6/1)	7.2					Sample	period: June 2025	
6/12	7.2					Campic	Month/Year	
0/13	7.2							
6/16	7.5	_					\sim	
6/17	ウェ				<u> </u>	Number of	excursions during this month:	
6/18	分 .S					(Over 9 exc	cursions in 6 months is a violation. Entry	
6/19	7.5					Point and D	Distribution excursions are cumulative).	
620	7.5						on' is any day in which the water quality	
6/23	7.5		<u> </u>			,	s) fall below the minimum set by the	
024	7.5				<u> </u>	State.		
6/25	7.5						erence emailed 7-9-25	
6/26	7.5				<u> </u>	⊢Refe	erence Tiville /	
927	7.5							
03	7.5		· ·				Minimum Water Quality	
			ļ	<u> </u>	-		Parameter(s) as set by State:	
			<u></u>		<u> </u>		pH 7.2	
		<u> </u>			<u> </u>			
			<u> </u>		—			
		ļ	<u> </u>	-	-			
	<u> </u>				 	.		
	ļ				-	<u> </u>		
		<u> </u>	<u> </u>	<u> </u>	 _ _	Print Name: Loni Weinnan Signature: Jon Muli-		
	 	 	 -			Signature: Ion M L		
 	 	├	-	-	+	Date:	-9-25	
└── No =	<u> </u>	Cureio	n) Tota	ı N'e		<u> </u>	OWP within 10 days after end of	
.40 -	No = N = Excursion) Total N's () Send to DWP within 10 days after end of sampling period							

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp