

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

of human services								
Day	рН	Alk	Phos	Sili	Y/N	<th>County: Linn Agency: Linn</th>	County: Linn Agency: Linn	
7/1	7.5					minimums been met for	ENTRY POINT	
7/2	7.5					this day?	EP-A	
7/3	7.4						PWS ID 4191707	
7/7	7.4							
7/8	7.4					PI	LEASANT VALLEY ELEM SD #55	
7/9	7.4				ļ		\	
7/10	7.4					Sample period: July 2025		
7/14	2.5		<u> </u>				Month/Year	
7/15	7.5		<u> </u>		-			
7/16	7. =	<u> </u>	<u> </u>			N	f averagions during this month:	
7/17	7.5		ļ		-	1	f excursions during this month:	
7/18	17.5		 	ļ	-	(Over 9 ex	cursions in 6 months is a violation. Entry	
1/21	75		 		 	Point and	Distribution excursions are cumulative). sion' is any day in which the water quality	
1/24	7.5		<u> </u>	 	┨	narameter	(s) fall below the minimum set by the	
7/25	17:2	<u> </u>	 	-	<u> </u>	State.	(b) fail bolow and minimum series	
7/2	 / 은	<u> </u>	-	<u> </u>	-	1		
200	14.5	1			1		ference emailed 8-5-25	
7/20	19.5	<u>'</u>	┧───	\vdash	1	1	referice	
7/2	175	 	1	 	-	1	Minimum Water Quality	
10	7.5	-]	Parameter(s) as set by State:	
		†		1			pH 7.2	
		1					PITE T.Z	
		1				1		
	1	1						
						Deint Na	ame: Loni Weinman	
					\perp	Signatu		
		<u> </u>			<u> </u>	Date: <u>_{</u>	· ·	
No =	No = N = Excursion) Total N's Send to DWP within 10 days after end of							
sampling period								