

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	Phos	Other	Y/N	< <have< th=""><th>County: Linn</th><th>Agency: LINN COUNTY</th></have<>	County: Linn	Agency: LINN COUNTY	
1	7.2					minimums	ENTRY	POINT	
2	7.2					been met for			
3						this day?	EP	-A	
4						PWS ID 4191712			
5	7.2					SEVEN OAK MIDDLE SCHOOL			
6	7.2								
7	7.2					Sample pr	riod: Febr	yary 2024	
8	7.2					Sample period: February 2024 Month/Year			
9									
10						Number of excursions during this month:			
11						(Over 9 excur	sions in 6 mon	ths is a violation. Entry	
12	7.2					Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.			
13	7.2								
14	7.2								
15	7.2								
16	7.2								
17						Reference			
18							5		
19						N	Ainimum Wate	er Quality	
20	7.2					Parameter(s) as set by State:			
21	7.2						pH 7.2		
22	7.2								
23	7.2								
24			2						
25									
26	7.2								
27	7.2					Print Name: Paula Shoulders			
28	7.2					Signature: Daula Shoulders Date & Phone #: 3/1/24 541.451.8456			
29									
30									
31			_			Send to sampling) days after end of	
No = N) Tota		r Pro	oram PO Box 14		OP 07203 0350	

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

dwp. dmce@dhsoha.state.or.u.