

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	7.2				
1 2 3 4					
3					
	7.2				
5	1.2 7.2 7.3				
6	7.2				
7	7.2				
8	1.2				
9					
10					
11					
12	7.2				
13	1.2				
14	7.2				
15	7.0				
16					
17					-
18	7.2				
19	7.2				
20	7.2				
21	7.2				
22	7.2				
20 21 22 23 24					
24					
25	7.2				
26	1.2				
27	7.7				
28					
29					
30					
31					
No = N	I = Exc	cursion) Tota	l N's	

<<Have minimums been met for this day?

County: Linn Agency: LINN COUNTY

ENTRY POINT

EP-A

PWS ID 4191712

SEVEN OAK MIDDLE SCHOOL

Sample period: Nov. 2014

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality Parameter(s) as set by State:

7.2 pΗ

Print Name: Paula Shoulders

Signature: Paula Date & Phone#: 11/30/24 541.451.8456

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/