

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.2				
2	7.2				
3	7.2				
4	7.2				
5					
6					
7	7.2				
8	7.2				
9	7.0				
10	7.2				
11	7.2				
12					
13					
14	7.2				
15	7.2				
16	7.2				
17	7.2				
18	7.2				
19					
20					
21					
22	7.2				
23	7.2				
24	7.2				
25	7.2				
26					
27					
28	7.2				
29	7.2				
30	7.2				
31					

<<Have minimums been met for this day?

County: Linn

Agency: LINN COUNTY

### ENTRY POINT

EP-A

PWS ID 4191712

SEVEN OAK MIDDLE SCHOOL

Sample period: April 2025  
Month/Year

Number of excursions during this month: \_\_\_\_\_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative).  
An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

#### Reference

Minimum Water Quality  
Parameter(s) as set by State:

pH 7.2

Print Name: Paula Shoulders  
Signature: Paula Shoulders  
Date & Phone#: 5/1/25 541.451.8456

Send to DWP within 10 days after end of sampling period

(No = N = Excursion) Total N's 0

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>