



## Water Quality Parameter Monitoring Form

## Lead &amp; Copper Rule Corrosion Control

Temp

Day	pH	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					
6					
7	7.9	120		17°	Y
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21	7.8	120		17°	Y
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					

(No = N = Excursion) Total N's 

<<Have minimums been met for this day?

County: Clackamas Agency: CLACKAMAS COUNTY

## ENTRY POINT

EP-A

PWS ID 4194670

OREGON TRAIL SD - BORING M&amp;D SCH

Sample period: November 2025  
Month/Year

Number of excursions during this month: 

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

## Reference

Minimum Water Quality Parameter(s) as set by State:

pH  7.2Print Name: Chelsea Lincoln LaneSignature: ChelseaDate & Phone#: 12/2/25 503 668-6442

Send to DWP within 10 days after end of sampling period