



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Temp

Day	pH	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5	7.6	120		17°	Y
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19	7.6	120		18°	Y
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					

(No = N = Excursion) Total N's

<<Have minimums been met for this day?	County: Clackamas Agency: CLACKAMAS COUNTY
	ENTRY POINT
	EP-A
	PWS ID 4194670
	OREGON TRAIL SD - BORING MID SCH
	Sample period: <u>December 2025</u> Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation.
Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH <input type="text" value="7.2"/>

Print Name: Chelsea Lincoln Lane
Signature: Chelsea
Date & Phone#: 1/2/26 503 668-6442
Send to DWP within 10 days after end of sampling period