

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
1 2 3 4 5 6	7.5				Y
3					
4					
5					
7					
8					
9	7.5				Y
10					,
11					
12					
13					
14					
15					
16	7.4				Y
17					•
18					
19					
20					
20 21					
22					
23	7.5	,			Y
24					
25					
26					
27				25	
28					
29					
30	7.5				Y
31					-
No = 1	V = Exc	cursion) Tota	l N's	0

(

< <have< th=""><th></th></have<>	
minimums	3
been met this day?	for
this day?	

County: Josephine Agency: JOSEPHINE COUNTY

ENTRY POINT

EP-A

PWS ID 4194765
BECKLIN HOLDINGS INC

Sample period: <u>August / 2021</u>

Month/Year

Number of excursions during this month: ____

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality neter(s) as set by State:
рН	7.3

Print Name: William LABARGE
Signature: William Faffing
Date & Phone#: 8/20/21 541-476-8871
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/