

System Name **Patio RV Park**

PWS ID# **41 00127**

Month/Year **FEB 1 2021** Entry Point **Source A**

Required Minimum Residual **0.3 mg/L**

Date	Time	Source(s) in use	Lowest free chlorine residual at entry point to distribution system (mg/L)	Notes
1	10A	PH		
2	10A	PH	9	2 c 2 gal
3	9A	PH	9	
4	9A	PH	8	
5	8A	PH	8	
6	9A	PH	7	
7	9A	PH	7	
8	9A	PH	6	3c up top tank *
9	9A	PH	6	
10	9A	PH	6	
11	10A	PH	6	
12	11A	PH	6	
13	11A	PH	6	
14	9A	PH	6	
15	9A	PH	6	
16	9A	PH	6	
17	9A	PH	6	
18	9A	PH	6	
19	10A	PH	6	
20	10A	PH	6	
21	10A	PH	6	
22	10A	PH	6	
23	10A	PH	6	
24	10A	PH	6	
25	10A	PH	6	
26	10A	PH	6	
27	10A	PH	6	
28	10A	PH	6	
29		PH	6	
30				
31				

Was the chlorine residual ever less than the required minimum residual of **3** mg/L? Yes No
 If yes, what was the longest time period until the required level was restored? _____ hours - If > 4 hours, Drinking Water Program to be notified by end of next business day.

GWS Serving 3,300 or Fewer
 If yes, did you monitor every four hours until the residual returned to _____ mg/L as required? Yes No

GWS Serving More Than 3,300
 Did continuous monitoring equipment fail at any time this reporting month? Yes No

Date continuous monitoring equipment failed:
2/7/2021
 Date it was returned to service:
2/7/2021

Attach those results and submit them with this form.

If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service as required? Yes No
 Attach grab sample results and submit them with this form.

Printed Name: **Fazy Shumate**
 Signature: *[Signature]*
 Date: **2/28/2021**

Title: **Manager**
 Phone #: **(541) 822-3586**

Operator Certification #: _____
 OR
 Small Groundwater System

*install new meter pump 2-7-2021