State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

Syster	n Name	City Of Oal	ridge PWSID# 41- 00582					
Month	MearJuly	12021 Entry F	Point: EPA	Wellfield Required Minimum Residual 0,2 mg/L				
Date	Time	Source(s)	in use		free chlor at entry po n system	oint to		Notes
1	9:27 Am	井山		2.61	m			C.M.E.
	2 8:25 Am #4 3 8:55 Am #1,2 H. 6			0.53 mal			CME	
3	8 Am	#1,24,6		0.50	mg	_		CME
5	9:20/Am			0.80	May			CME
6		# 246		0.63 mgl			CME	
7	The second of the Party of the			0.69 mgl			CME	
8	8:24 Am	#1.2+4		0,66	mal	_		CME
9	C . 191		·	0.68	mal			CME
10	9:00am	#2,4+6		0.63 mal			CME	
11	JUHM			0.66 mgL			CME	
12	10:46Am	*2,4+6			nal	-		CME
				0.59 mgL			CME	
14	0.20 Am	#2 4+6			mal			CME
	8:30 Am	#2.4+6		0.61	mal			CME
16	9:00An	1 0 11 1			ngt			CME
17				0.56	mg (CME
				0,53 mal			Cusiz	
10 0 0 0				0158 Wel			CME	
19 9:54 # 2 4 6 20 8:51/m # 2 4 6				X.57 mal			C.M.E.	
				2.59 mgl			C.M.E.	
				8,57 mgl			CME	
				0.59 mail			CME	
				8,55	May	-		CME
				0.60	MB			CME
				0.62	ma			CME
26 B: 31 Am = 2, 4 + 6 27 B: 46 Am = 4				0.64	mal	gapa		CME
28		井山		0.61	mal			CME
29 8:30 am #24+6				0.60	mal			CME
30	b, 13/20	# 246		0.65	mgi	-		CME
-	10:37 in	#47		8,60	mgl	-		CME
-		F 7		0.55	mgl	_		CME
Was the chlorine residual ever less than the required minimum residual of \(\frac{1}{2} \) mg/L? \(\triangle \) Yes \(\triangle \) No If yes, what was the longest time period until the required level was restored? hours								
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300								00
intil the residual returned to mg/L? reporting mo				monitoring equipment fail at any time this h? Yes No				Date continuous monitoring equipment failed:
Attach those results and submit them with his form.				e grab samples collected every four hours until the smonitoring equipment was returned to service? Yes No				/ / Date it was returned to
100			Attach grab sar	tach grab sample results and submit them with t			this form.	service: / /
inted Name: Floyd Stalcup			Title tailiby when III				Operator Certification #: 7-98999	
	Jeans E:					- 1		
ate: E	0	2021	Phone #: (541)974 - 3942			42	OR Small Groundwater System	
DWP ROBEX 17450								