## State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name: Bella Casa Mo		Bella Casa Mobile Hor	ne Park	<b>PWS ID#</b> 41 - 01005	
Month/Year:		January 2023	Entry Point: Kitchen Sink in Rec Rm	Required Minimum Residual: 0.60 mg/L	
Date	Time	Source(s) in Use	Lowest free chlorine residual at entry point to distribution system (mg/L)	N	lotes
1	2:00:00 PM		0.62		
2	10:00:00 AM		0.66		
3	10:00:00 AM	( )	0.73		
4	10:00:00 AM	`````	0.70		
5	6:00:00 AM		0.67		
6	2:00:00 PM	`````	0.68		
7	10:00:00 AM	`````	0.72		
8	6:00:00 AM	· · · · /	0.75		
9	6:00:00 PM		0.77		
10	6:00:00 PM	· · · · /	0.75		
11	6:00:00 PM	`````	0.77		
12	6:00:00 PM	· · · · · · · · · · · · · · · · · · ·	0.72		
13	10:00:00 AM 10:00:00 AM		0.73		
14		· · · · · · · · · · · · · · · · · · ·	0.68		
15 16	6:00:00 AM 2:00:00 PM	· · · · /	0.63 0.73		
17	2:00:00 PM 2:00:00 PM	````	0.83		
18	6:00:00 AM		0.67		
19	6:00:00 AM		0.82		
20	6:00:00 PM		1.26		
20	10:00:00 AM	· · · · · · · · · · · · · · · · · · ·	1.20		
22	10:00:00 AM	· · · · · · · · · · · · · · · · · · ·	1.11		
23	2:00:00 PM		0.92		
24	6:00:00 AM		0.71		
25	6:00:00 AM	· · · · · · · · · · · · · · · · · · ·	0.61		
26	6:00:00 AM	· · · · · · · · · · · · · · · · · · ·	0.61		
27	10:00:00 AM	· · · · /	1.11		
28	2:00:00 PM	, ,	0.85		
29	2:00:00 PM	· · · · · · · · · · · · · · · · · · ·	0.80		
30	6:00:00 PM	WELL (L15434)	0.66		
31	2:00:00 PM	WELL (L15434)	0.65		
Was the chlorine residual ever less than the required minimum residual of <b>.60</b> mg/L Yes _ <u>X</u> No If yes, what was the longest time period until the required level was restored? hours					
GWS Serving 3,300 or Fewer			GWS Serving Mo	ore Than 3,300	
If yes, did you monitor every four hours until the residual returned to <b>.60</b> mg/L?			Did continuous monitoring equipment fail at any time this reporting month?YesNo		Date continuous monitoring equipment failed: / /
Attach those results and submit them with this form.			If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service? YesNo Attach grab sample results and submit them with this form.		Date it was returned to service:
Printed Name: Dan Reitz Title: Vice President					
r inite(	inalle.			Operator Cartification #: D-6529 T-6529	
			Oregon Water Services, Inc. Phone#: (541) 342-1718	Operator Certification #: D:6528, T:6528 OR	
Date:	2/7/2023			Small Ground Water System	