State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name Beaver Creek RV Resort PWS ID# 4 1 01333							
Month/Year _09/2021 Entry Point: EP-B Required Minimum Residual 1.2 mg/L							
Date	Time	Source(s) in use		Lowest free chlorine residual at entry point to distribution system (mg/L)		Notes	
1	0850			1.3			
2	0845			1.3			
3	0850			1.2			
4	0830			1.5			
5	0845			1.5			
6	0930			1.4			
7	0840			1.4			
8	0850			1.3			
9	0845			1.3			
10	0830	-		1.2			
11	0900			1.5			
12	0810			1.5			
13	0840			1.5			
14	0910			1.4			
15	0900			1.3			
16	0855			1.3			
. 17	0900			1.2			
18	0830			1.2			
19	0830			1.2			
20	0900			1.5			
21	0910			1.5			
22	0855			1.4			
23	0850			1.4			
24	0850			1.3			
25	0900			1.4			
26	0900			1.4			
27	0900			1.3			
28	0910			1.3			
29	1040			1.2			
30	0850			1.2			
31							
Was the chlorine residual ever less than the required minimum residual of 1.2 mg/L? Yes No If yes, what was the longest time period until the required level was restored? hours							
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300							
				is monitoring equipment fail at any time this at the state of the sta		Date continuous monitoring equipment failed:	
Attach those results and submit them with this form.			If yes, were grab samples collected every four hour continuous monitoring equipment was returned to s Yes No			Date it was returned to service:	
			Attach grab sample results and submit them wit		vith this form.	1 1	
Printed N	Name: Payl	Duffney	Title	e: Manager	Operato	r Certification #:	
Signature: Phone #: (541) 479-7445 OR							
Date: 10	Date: 10 / 07 / 2021 Small Groundwater System ⊠						