State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name Humbug Mtn SP PV					WS ID# 41 9	1018	
Month/Year /0 / 2023 Entry Point: WTP-A Required Minimum Residual 0.3 mg/L							
Date	Time	Source(s) in		Lowest free chlorine residual at entry point to distribution system (mg/L)		Notes	
1.	8:25 A	·		.34	Shop	CW	
2	8:30 4		-	.60	Shop	ÉR	
3	8:20A		*******	.34	Shop	SH	
4	8:15A			39	Shop	5/-	
5	8;15 A			*32	Slin	SH	
6	8:20A	 		.36	Shop	. 5//	
7				112		· 5/-	
	8:20A	 		2	Shep		
8	B:35A	1		, 37	Shop		
9	% ; 20 #	<u> </u>		1.69	Shap	ER,	
10	8:30A	<u> </u>		.43	5hsp	SH	
11	8:20A	<u> </u>		,32	Shop	SH	
12	8;20A			.59	Shop	514	
13	8:20A			.36	5hep	5/1	
14	8:20A			e 35	Shop	SH	
15	8:00 A			,35	Shoo	611)	
16	8:10A			1.0		dw	
17		+		.37	15/100	514	
	8:20 A				Shop'		
18	8:20 A	 		.55	Shop	5/-	
19	8:40A	<u> </u>		055	Shop	514	
20	8:20A	1		.52	Shap	SH	
21	8:20 A			.46	Shap	5/1	
22	8:00A			156	Shop	gω	
	8-00A			,51	TAND	32	
24	8:05 A			.82	Shop	81	
25	8:20 A		,	.60	Shop	Sit	
26	8:25/			.72	17	-5/1	
27	8:20A			. 68	Shop	514	
28	8:20A	 		1 2 /			
	0,507	 		66	Shop	SIT	
29	8:00A	1		7.2	Shop Si	gw	
	8-00A		·····	173	Shap	Ch	
31	8:25A	<u> </u>		.94	5hsp	511	
Was th	e chlorine res	sidual ever less than the	required minimu	ım residual of 0.3 mg/L? 🔲 \	Yes 🔯 No		
If yes, what was the longest time period until the required level was restored? hours – If > 4 hours, Drinking Water Program to be notified by end of next business day.							
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300						300	
1	_	·	Did continuous	·			
If yes, did you monitor every four hours until the residual returned to mg/L			Did continuous monitoring equipment fail at any time this reporting month? Yes No Pate continuous monitoring equipment failed:				
`			If yes, were grab samples collected every four hours until the				
Attach those results and submit them with			continuous monitoring equipment was returned to service as Date it was returned to				
this form.			required?				
l			Attach grab sar	Attach grab sample results and submit them with this form.			
Printed Name: Steve Huster			Tille: Park Ranger		Operato	Operator Certification #:	
Signature: Atme Thates			Phone #: (54/) 332-6774		OR		
			FIIU	Ne #: (3サ/) ファム・ロイイア	1	_	
Date:	11101	123	!		Small Groundwater System 🚫		