State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name OPRD Cove Park - Deschutes PWS ID# 4 1 91036						
Month/Year July 2021 Entry Point: Required Minimum Residual .5 mg/L						
Date	Time	Source(s) in use		Lowest free chlorine residual at entry point to distribution system (mg/L)	Notes	
1	9AM	AA-Well#1		0.85	Taken at shop	
2	9AM	AA-Well#1		0.76	Taken at shop	
3	11AM	AA-Well#1		0.69	Taken at shop	
4	10AM	AA-Well#1		0.58	Taken at shop	
5	8AM	AA-Well#1		0.51	Taken at shop	
6	8AM	AA-Well#1		0.52	Taken at shop	
7	9AM	AA-Well#1		0.57	Taken at shop	
8	8AM	AA-Well#1		0.57	Taken at shop	
9	8AM	AA-Well#1		0.76	Taken at shop	
10	7AM	AA-Well#1		0.90	Taken at shop	
11	10AM	AA-Well#1		0.84	Taken at shop	
12	10AM	AA-Well#1		0.79	Taken at shop	
13	9AM	AA-Well#1		0.78	Taken at shop	
14	9AM	AA-Well#1		0.81	Taken at shop	
15	9AM	AA-Well#1		0.61	Taken at shop	
16	8AM	AA-Well#1		0.52	Taken at shop	
17	11AM	AA-Well#1		0.60	Taken at shop	
18	3PM	AA-Well#1		0.76	Taken at shop	
19	10AM	AA-Well#1		0.67	Taken at shop	
20	9AM	AA-Well#1		0.81	Taken at shop	
21	9AM	AA-Well#1		0.52	Taken at shop	
22	9AM	AA-Well#1		0.55	Taken at shop	
23	7AM	AA-Well#1		0.61	Taken at shop	
24	7AM	AA-Well#1		0.61	Taken at shop	
25	8AM	AA-Well#1		0.73	Taken at shop	
26	9AM	AA-Well#1		0.51	Taken at shop	
27	10AM	AA-Well#1		1.06	Taken at shop	
28	11AM	AA-Well#1		0.84	Taken at shop	
29	7AM	AA-Well#1		1.01	Taken at shop	
30	2PM	AA-Well#1		0.76	Taken at shop	
31	9AM	AA-Well#1 0.91 Taken at shop				
Was the chlorine residual ever less than the required minimum residual of 0.5 mg/L? Yes X No						
If yes, what was the longest time period until the required level was restored? hours – If > 4 hours, Drinking Water Program to be notified by end of next business day.						
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300						
If yes, did you monitor every four hours until the residual returned to mg/L as required? Yes No			Did continuous monitoring equipment fail at any time the reporting month? Yes No			Date continuous monitoring equipment failed:
			If yes, were grab samples collected every four hours until the		1 1	
Attach those results and submit them with			continuous monitoring equipment was returned to service as Date it was returned to			
this form.					service:	
Attach grab sample results and submit them with this form.						1 1
Printed N	Name: Shawi	nae Stanton	Title: Park Specialist		Operator Certification #:	
Signature: Phone #: (541) 546-3412 OR						OR
Date: 08/03/2021 Small Groundwater System X						