State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name OPRD Cove Park - Deschutes PWS ID# 4 1 91036							
Month/Year Dec 2021 Entry Point: Required Minimum Residual .5 mg/L							
Date	Time Source(s) i		n use	Lowest free chlorine residual at entry point to distribution system (mg/L)		Notes	
1	1 10AM AA-Well#1		-	0.59	Taken at shop		
2	10AM	AA-Well#1		0.55	Taken at shop		
3	9AM	AA-Well#1		0.60	Taken at shop		
4	9AM	AA-Well#1		0.53	Taken at sh	юр	
5	9AM	AA-Well#1		0.57	Taken at sh	qop	
6	10AM	AA-Well#1		0.52	Taken at sh		
7	10AM	AA-Well#1		0.73	Taken at sh	ор	
8	10AM	AA-Well#1		0.66	Taken at sh		
9	9AM	AA-Well#1		0.68	Taken at sh	•	
10	9AM	AA-Well#1		0.75	Taken at sh		
11	8AM	AA-Well#1		0.73	Taken at sh		
12	9AM	AA-Well#1		0.63	Taken at sh	<u> </u>	
13	10AM	AA-Well#1		0.51	Taken at sh	<u> </u>	
14	10AM	AA-Well#1		0.54	Taken at sh		
15	9AM	AA-Well#1		0.62	Taken at sh		
16	9AM	AA-Weli#1		0.63	Taken at shop		
17	11AM	AA-Well#1		0.76	Taken at sh		
18	10AM	AA-Well#1		0.74	Taken at sh		
19	9AM	AA-Well#1		0.69	Taken at sh		
20	9AM	AA-Well#1		0.71	Taken at sh		
21	9AM	AA-Weil#1		0.77	Taken at sh		
22	9AM	AA-Well#1		0.79	Taken at shop		
23	8AM	AA-Well#1		0.77	Taken at shop		
24	8AM	AA-Well#1		0.75	Taken at shop		
25	10AM	AA-Well#1		0.74	Taken at shop		
26	8AM	AA-Well#1		0.78	Taken at shop		
27	10AM	AA-Weli#1		0.68	Taken at shop		
28	10AM	AA-Well#1		0.62	Taken at shop		
29	10AM	AA-Well#1		0.66	Taken at shop		
30	10AM	AA-Well#1		0.76	Taken at shop		
31	9AM	AA-Well#1		0.68	Taken at shop		
Was the chlorine residual ever less than the required minimum residual of 0.5 mg/L? Yes X No							
If yes, what was the longest time period until the required level was restored? notified by end of next business day. hours – If > 4 hours, Drinking Water Program to be							
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300							
If yes, did you monitor every four hours			Did continuous monitoring equipment fail at a			Date continuous monitoring	
until the residual returned to mg/L as required? ☐ Yes ☐ No			reporting month? Yes No If yes, were grab samples collected every four hour		ary unio uno	equipment failed:	
					r houre until the		
Attach those results and submit them with			continuous monitoring equipment was returned to serv			Date it was returned to	
this form.			required? Yes No		34 10 001 1100 40	service:	
			Attach grab sample results and submit them w		with this form.	1 1	
Printed Name: Shawnae Stanton Title: Park Specialist Operator Certification #:							
Signature: Phone #: (541) 546-3412					OR		
Date: 0	Date: 01/03/2022					Small Groundwater System X	