

State of Oregon Drinking Water Program
Monthly Disinfection Report for Ground Water Systems

System Name Restful Haven Health Club

PWS ID# 41 91609

Month/Year Sept/2023 Entry Point: WTP-A

Required Minimum Residual 1



| Date | Time | Source(s) in use | Lowest free chlorine residual at entry point to distribution system (mg/L) | Notes |
|------|--------|--------------------|--|-----------------|
| 1 | 9:30AM | Clubhouse Restroom | 1.1 | Robert Janssen |
| 2 | 9:10AM | Clubhouse Restroom | 1.1 | Robert Janssen |
| 3 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 4 | 9:00AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 5 | 9:30AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 6 | 9:30AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 7 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 8 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 9 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 10 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 11 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 12 | 9:30AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 13 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 14 | 9:30AM | Clubhouse Restroom | 1.2 | Robert Janssen |
| 15 | 8:30AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 16 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 17 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 18 | 9:30AM | Clubhouse Restroom | 1.3 | Robert Janssen |
| 19 | 9:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 20 | 9:00AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 21 | 9:30AM | Clubhouse Restroom | 1.3 | Robert Janssen |
| 22 | 9:30AM | Clubhouse Restroom | 1.3 | Robert Janssen |
| 23 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 24 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 25 | 9:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 26 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 27 | 8:30AM | Clubhouse Restroom | 1.3 | Marshall Miller |
| 28 | 9:30AM | Clubhouse Restroom | 1.3 | Robert Janssen |
| 29 | 9:30AM | Clubhouse Restroom | 1.3 | Robert Janssen |
| 30 | 9:30AM | Clubhouse Restroom | 1.2 | Marshall Miller |
| 31 | | | | |

Was the chlorine residual ever less than the required minimum residual of 1.0 mg/L? Yes No

If yes, what was the longest time period until the required level was restored? _____ hours - If > 4 hours, Drinking Water Program to be notified by end of next business day.

GWS Serving 3,300 or Fewer

If yes, did you monitor every four hours until the residual returned to _____ mg/L as required? Yes No

Attach those results and submit them with this form.

GWS Serving More Than 3,300

Did continuous monitoring equipment fail at any time this reporting month? Yes No

Date continuous monitoring equipment failed: / /

If yes, were grab samples collected every four hours until the continuous monitoring equipment was returned to service as required? Yes No

Date it was returned to service: / /

Attach grab sample results and submit them with this form.

Printed Name: George Marsh

Title: MSR President

Operator Certification #: WTP-A

Signature: 

Phone #: (503) 647-2449

OR

Date: 10 / 01 / 2023

Small Groundwater System

December 19, 2012